

Catastrophic Turbine Failure

Turbine #10 of the 11-turbine Searsburg wind facility in Searsburg VT collapsed on September 15 in high wind conditions. One of the turbine blades hit the base causing the tower to buckle and the nacelle and rotor assembly to crash to the ground.